

劣化数量表 東面1

爆裂				
NO	階数	W	H	m ²
1	4	0.3	0.3	0.09
計				0.09
欠損				
計				0.00

モルタル浮き				
NO	階数	W	H	m ²
1	4	0.6	0.6	0.36
2	4	0.6	0.5	0.30
3	4	0.5	1.0	0.50
4	4	0.6	1.0	0.60
5	4	0.5	0.5	0.25
6	4	0.8	0.5	0.40
7	3	0.5	0.7	0.35
8	3	0.6	0.6	0.36
9	3	0.6	0.8	0.48
10	2	0.4	0.8	0.32
11	2	0.5	0.5	0.25
12	2	0.8	1.0	0.80
13	2	0.8	0.8	0.64
14	2	0.5	1.0	0.50
15	2	0.6	0.5	0.30
16	2	1.0	0.5	0.50
17	1	1.5	2.2	3.30
18	1	1.5	1.5	2.25
19	1	1.8	1.2	2.16
20	1	1.5	0.6	0.90
21	1	1.5	0.8	1.20
22	1	0.6	0.6	0.36
計				17.08

劣化数量表 西面1

爆裂				
NO	階数	W	H	m ²
1	4	0.3	0.2	0.06
2	4	0.5	0.2	0.10
3	4	0.5	0.2	0.10
計				0.26
欠損				
計				0.00

モルタル浮き				
NO	階数	W	H	m ²
1	4	0.3	0.8	0.24
2	4	0.6	0.6	0.36
3	3	0.2	1.5	0.30
4	3	0.6	0.8	0.48
5	2	1.5	0.3	0.45
6	2	0.4	0.8	0.32
7	2	0.4	0.8	0.32
8	1	0.6	0.6	0.36
9	1	1.0	0.8	0.80
10	1	0.8	0.5	0.40
11	1	1.0	1.0	1.00
12	1	0.6	2.0	1.20
計				6.23

劣化数量表 西面2

ひび割れ			
NO	階数	L	
1	4	0.7	
2	4	0.7	
3	4	0.7	
4	4	0.8	
5	4	0.7	
6	4	0.7	
7	4	0.7	
8	4	2.3	
9	4	0.7	
10	4	2.2	
11	4	0.7	
12	4	0.7	
13	4	0.7	
14	4	0.9	
15	4	0.7	
16	4	0.7	
17	3	0.7	
18	3	0.7	
19	3	0.7	
20	3	0.7	
21	3	2.2	
22	1	1.0	
23	1	2.2	
24	1	0.8	
計		23.6	

劣化数量表 南面3

ひび割れ			
NO	階数	L	
41	4	0.7	
42	4	0.7	
43	4	0.7	
44	4	0.7	
45	4	0.7	
46	4	0.7	
47	4	0.7	
48	4	0.7	
49	4	0.7	
50	3	0.7	
51	3	0.7	
52	3	0.7	
53	3	0.7	
54	3	0.7	
55	3	0.7	
56	3	0.7	
57	3	0.7	
58	3	0.7	
59	3	0.7	
60	3	0.7	
61	3	0.7	
62	3	0.7	
63	2	0.7	
64	2	0.7	
65	1	0.7	
66	1	0.7	
67	1	1.2	
68	1	0.7	
69	1	0.2	
70	1	0.2	
71	1	1.4	
72	1	0.7	
1~40 計		28.1	
計		50.7	

劣化数量表 北面1

爆裂				
NO	階数	W	H	m ²
計				0.00
欠損				
1	1	0.1	0.5	0.05
計				0.05

モルタル浮き				
NO	階数	W	H	m ²
1	4	1.0	0.9	0.90
2	4	0.8	0.5	0.40
3	4	1.3	0.7	0.91
4	3	2.0	0.7	1.40
5	3	0.6	0.6	0.36
6	3	1.0	0.5	0.50
7	3	0.3	1.0	0.30
8	3	1.7	0.6	1.02
9	3	0.8	0.4	0.32
10	3	0.4	0.8	0.32
11	2	0.6	0.6	0.36
12	2	0.8	0.4	0.32
13	2	0.6	0.6	0.36
14	2	0.8	1.0	0.80
15	2	0.3	1.3	0.39
16	2	0.5	1.0	0.50
17	2	0.6	0.6	0.36
18	2	0.5	1.6	0.80
19	1	0.7	1.0	0.70
20	1	1.3	0.8	1.04
21	1	1.0	0.7	0.70
22	1	0.8	0.4	0.32
23	1	1.0	0.8	0.80
24	1	0.6	1.4	0.84
25	1	1.6	0.7	1.12
26	1	0.8	2.0	1.60
27	3	3.0	0.2	0.60
28	3	0.8	0.7	0.56
29	3	0.4	0.8	0.32
30	3	2.2	0.2	0.44
31	3	1.0	0.6	0.60
32	3	1.6	0.2	0.32
33	3	0.5	0.8	0.40
34	3	0.8	0.5	0.40
35	2	0.7	1.2	0.84
36	2	0.8	0.5	0.40
37	2	0.6	1.2	0.72
38	2	0.4	1.5	0.60
39	2	2.0	0.2	0.40
40	2	0.7	0.8	0.56
小計				24.60

劣化数量表 北面2

モルタル浮き				
NO	階数	W	H	m ²
41	2	2.0	0.7	1.40
42	2	1.5	0.4	0.60
43	2	0.4	2.0	0.80
44	1	0.4	1.0	0.40
45	1	1.0	0.4	0.40
46	1	2.2	0.3	0.66
47	1	2.0	0.8	1.60
48	1	0.5	0.7	0.35
49	1	1.0	1.2	1.20
1~40 計				24.60
計				32.01

ひび割れ				
NO	階数	L		
1	4	0.7		
2	4	0.7		
3	4	1.3		
4	4	0.9		
5	4	0.7		
6	4	0.7		
7	4	0.7		
8	4	0.7		
9	4	0.7		
10	4	0.7		
11	4	0.7		
12	4	0.7		
13	4	0.5		
14	4	0.7		
15	4	0.5		
16	4	0.7		
17	4	0.7		
18	4	0.7		
19	4	0.7		
20	4	0.7		
21	4	0.7		
22	3	1.0		
23	3	1.0		
24	3	0.7		
25	3	0.7		
26	3	0.4		
27	3	0.7		
28	3	0.8		
29	3	0.7		
30	3	1.0		
31	3	1.0		
32	3	1.0		
33	3	0.6		
34	3	0.7		
35	3	0.7		
36	3	0.7		
37	2	0.7		
38	2	1.3		
39	2	0.9		
40	2	0.7		
小計		30.4		

劣化数量表 北面3

ひび割れ			
NO	階数	L	
41	2	0.7	
42	2	0.4	
43	2	1.0	
44	2	1.0	
45	2	0.7	
46	2	0.7	
47	2	0.7	
48	1	1.2	
49	1	0.7	
50	1	0.7	
51	1	0.7	
52	1	0.7	
53	1	0.7	
54	1	0.7	
55	1	1.0	
56	1	1.5	
57	1	0.9	
58	1	1.5	
59	1	0.8	
60	1	0.6	
61	1	0.7	
62	1	0.8	
63	1	0.7	
64	1	0.7	
65	1	0.7	
66	1	1.8	
67	4	0.7	
68	4	0.7	
69	4	0.7	
70	4	0.7	
71	4	0.9	
72	4	0.7	
73	4	0.7	
74	4	0.7	
75	4	0.6	
76	4	1.0	
77	4	0.8	
78	4	0.7	
79	4	0.7	
80	4	0.7	
小計		32.6	

ひび割れ			
NO	階数	L	
81	4	0.7	
82	4	0.7	
83	4	0.7	
84	4	0.9	
85	4	0.7	
86	4	1.0	
87	4	0.7	
88	3	0.7	
89	3	0.7	
90	3	0.7	
91	3	0.7	
92	3	0.7	
93	3	0.6	
94	3	1.0	
95	3	1.0	
96	3	0.7	
97	3	1.0	
98	3	1.0	
99	3	0.7	
100	3	0.7	
101	3	0.7	
102	3	1.0	
103	3	0.7	
104	3	0.7	
105	3	0.7	
106	2	1.8	
107	2	1.6	
108	2	1.2	
109	2	0.6	
110	2	1.0	
111	2	0.7	
112	2	0.7	
113	2	1.5	
114	2	0.4	
115	2	0.4	
116	2	0.7	
117	2	1.5	
118	1	0.7	
119	1	0.7	
120	1	1.0	
小計		33.9	

劣化数量集計表

【各種集計結果】

	種別					
	浮き	ひび割れ	欠損	爆裂	白華現象	塗膜の剥がれ
東面	17.08	11.1	0.00	0.09	0	3
西面	6.23	23.6	0.00	0.26	0	7
南面	8.92	50.7	0.00	5.24	0	54
北面	32.01	108.2	0.05	0.00	2	7
合計	64.24	193.6	0.05	5.59	2	71
単位	m ²	m	m ²	m ²	箇所	箇所

【浮き率結果】

外壁面	調査面	東面	西面	南面	北面	
	調査面積(m ²)	107.7	107.7	414.5	364.9	
	浮き率(%)	15.9 %	5.8 %	2.2 %	8.8 %	

【総計】

トータル		
調査面積	994.8	m ²
浮き	64.24	m ²
浮き率	6.5	%
ひび割れ	193.6	m
欠損	0.05	m ²
爆裂	5.59	m ²
白華現象	2.0	箇所
塗膜の剥がれ	71.0	箇所